





QA Testing Ceertification Co., Ltd.

TEST REPORT

Test Report No.: QA2019111301-S
Sample Name: Sun Room 3.7X2.9m
Model: SR
Date (s) of tests: 2019-11-07—2019-11-13
Manufacturer: NINGBO SUNRISE OUTDOOR PRODUCTS LTD

TEST REPORT BS EN 1991-1-3:2003+A1: 2015 Eurocode 1 – Actions on structures – Part 1-3: General actions – Snow loads	
Testing Laboratory Name	QA Testing CeertificationCo., Ltd
Applicant's Name	NINGBO SUNRISE OUTDOOR PRODUCTS LTD
Address	NO.188, HUI SHUI ROAD, LUOTUO TOWN, ZHENHAI DISTRICT, NI NGBO CITY
Manufacturers	NINGBO SUNRISE OUTDOOR PRODUCTS LTD
Address	NO.188, HUI SHUI ROAD, LUOTUO TOWN, ZHENHAI DISTRICT, NI NGBO CITY
Test specification	
Standard.....:	EN 1991-1-3:2003+A1:2015
Test procedure.....:	EN
Council directives.....:	CE
Non-standard test method.....:	N/A
Test item description.....:	Sun Room 3.7X2.9m
Model and/or type reference.....:	SR
Test By: Signature	Review By: Signature
 Name: Qingang Date: 2019-11-13	 Name: Zhanglin Date: 2019-11-13

General remarks:

1. This report shall not be reproduced, except in full, without the written approval of the Issuing testing laboratory.
2. The test results presented in this report relate only to the object tested.

Possible test case verdicts:

- test case does not apply to the test object or the requirement is not tested: N
- test object does meet the requirement: P(Pass)
- test object does not meet the requirement: F(Fail)

Summary of test results (information/comments):

All tests were performed in according with the above mentioned standard.

Summary of test:

Model SR was tested with full tests.

Angle of roof pitch α	$15^\circ < \alpha < 30^\circ$
------------------------------	--------------------------------

	Requirement-Test	Result-Remark	Verdict
Type of snow	Bulk weight density [kg/m ²]		
Fresh	150 kg	150 kg	P
Settled (several hours or days after its fall)	10 Hour	10 Hour	P

General product information:

Sun Room 3.7X2.9m

Copy of marking plate:




Photo:



Photo:

